

ELECTRICAL SAFETY PRODUCT RECALL



Date: 7th March 2008

Supplier Name: Bromic Pty Limited

Product Info: Bromic commercial display refrigerators.

Models affected:

On data label:	USS500DTKL	USS660DTKL	USS1000DTKL
(also known as)	(GM0500L)	(GM0660L)	(GM1000L)
	(3735121)	(3735122)	(3735123)

Defect Details: A wire connection within the top light box assembly may, in extreme cases, overheat and cause a fire.

This recall applies to the above models purchased anywhere in Australia since 1st September 2003.

Consumer Action: Disconnect the fridge from the power supply immediately. Please have the model and serial number (located at rear of refrigerator) ready and call Bromic Pty Limited on 1300 276 642, Monday to Friday: 9am to 5pm EST to register your details. Bromic will arrange for a service technician to call and check your product free of charge.

Market Coverage: National

Recall coverage: National

**See www.recalls.gov.au for
Australian product recall information**